

SERVICE BULLETIN SB00.29

Serial Numbers: AB46; 2007-2073

Machines/Models:AB46,LX series

LX series; 3384-3548

THE PROCEDURE SPECIFIED IN THIS BULLETIN **MUST** BE PERFORMED IMMEDIATELY

DATE: October 19, 2000

PURPOSE: Verify Proper Wheel Installation


PROCEDURE REQUIRED: Inspect the wheels for the proper weld

REIMBURSEMENT: UpRight will reimburse the owner of record for 1 hour of labor at \$60.00 per hour and for travel (up to 100 miles at .50 cents per mile). Reimbursement will be made upon receipt by UpRight of your completed Warranty Claim Form. Please reference SB00.29 on your Warranty Claim Form.

READ ALL INSTRUCTIONS AND REVIEW ALL FIGURES BEFORE PERFORMING THE FOLLOWING INSTRUCTIONS.

PROCEDURE 1

- 1. Inspect the rim to center support attachment welds and compare to Figures 1 and 2.
- 2. If the rim on your machine matches the picture in Figure 1 no further action is necessary.
- 3. If the rim on your machine matches the picture in Figure 2 contact Product Support immediately at 1(800) 926-5438.






Figure 1 Figure 2

If you have any questions regarding this Service Bulletin, please contact the UpRight Product Support Department by telephone at (800) 926-5438 from within the USA or at (559) 891-5200 outside the USA or by FAX at (559) 891-8931.

Page 1 of 1 SB 00.33