

Service Bulletin :
AB46E Hydraulic Pump

Reference: SAU10.04

Date of Issue: 14th May 2010

Affected Machines: AB46E

Serial numbers: AB46 10025 to 10120

Purpose: As a result of findings from our machine cycling programme, we have identified an opportunity to reduce the electrical current loading on the main hydraulic pump drive motor, of the AB46E machine, by implementing a modification to the pump hydraulic circuit.

Instructions for carrying out the modification are given in the attached Pdf file below.

It will be beneficial if this modification is introduced at the next routine machine service / examination.

Parts required: Please see the attached installation instructions below.

Procedure:



IP-0260607.pdf

Technical support:

If required, support and advice is available by contacting the Snorkel Technical Support Dept. for assistance.

UK / Europe: neil.brown@upright.com

USA: Tony.Deatherage@snorkelusa.com

Australia / New Zealand: DFloyd@snorkel.com.au

simon@snorkel.co.nz

Asia: Fw.fun@tanfieldgroup.com

Japan: sakuma@uprightjp.com