



SERVICE BULLETIN SB02.04

Machines/Models: X series With Entry Gate **Serial Numbers:** 1001 - 20116

THE PROCEDURE SPECIFIED IN THIS BULLETIN **MUST** BE PERFORMED AT THE NEXT 30 DAY MAINTENANCE INTERVAL

DATE: December 1, 2002

PURPOSE: To simplify the operation and improve the safety of the Gate Latch Assembly

REIMBURSEMENT: UPRight will reimburse the for .1 HOUR of labor at 60.00 per hour. Reimbursement will be made upon receipt by UpRight INC. of your warranty claim form


Parts Required:

1. (1) Gate latch Assy part # 003570-005

READ THE INSTRUCTIONS AND REVIEW THE FIGURE BEFORE PERFORMING THE FOLLOWING INSTALLATION.

OPERATIONS REQUIRED, X MACHINES WITH ENTRY GATE ONLY.

1. Remove and discard gate latch assembly.
2. Install new gate latch assembly part # 003570-005.



If you have any questions regarding this Service Bulletin, please contact the UpRight Product Support Department by telephone at (800) 926-5438 from within the USA or at (559) 662-3900. From Europe countries + 353 (0) 1 620 9300 (Ireland)