

SERVICE BULLETIN SB00.05

Machines/Models: AB46RT DF

Serial Numbers: 1000-2000

THIS BULLETIN IS **OPTIONAL**.

DATE: March 30, 2000

PURPOSE: Enhance the Engine performance

PROCEDURE REQUIRED: Replace the Carbureted system with Fuel Injection

PARTS REQUIRED: 1 each - kit part number SB00.05

KIT INCLUDES: 1 each -068873-044 Throttle Body Kit

1 each -068873-015 Thermostat

1 each -068873-016 Gasket

1 each -012797-000 Switch

REIMBURSEMENT: UpRight will reimburse the owner of record for 2.5 hours of labor at \$60.00 per hour. Reimbursement will be made upon receipt by UpRight of your completed Warranty Claim Form. Please reference SB00.05 on your Warranty Claim Form.

PROCEDURE: Read all instructions thoroughly before starting.

SEE ATTACHED FOR COMPLETE INSTRUCTIONS

If you have any questions regarding this Service Bulletin, please contact the UpRight Product Support Department by telephone at (800) 926-5438 from within the USA or at (559) 891-5200 outside the USA or by FAX at (559) 891-8931.