

## SERVICE INFORMATION LETTER SI 01.04

**Machines/Models:** SL26/30RT/SL, XRT **Serial Numbers:** See Below

DATE: July 30, 2001

PURPOSE: Identify the Model and Serial of White Hydraulic Brakes with potential weak braking at maximum gradeability.

PROCEDURE REQUIRED: Inspect and Record the Model and Serial number of the rear brake/brake motor assembly.

PROCEDURE: Mandatory.

PARTS REQUIRED: To Be Determined

WARRANTY REIMBURSEMENT: Warranty consideration will be given for SI01.05.

1. Perform the following inspection.
2. Using a flashlight and mirror (if necessary) record the model and serial number in the following space corresponding to the position.

Machine Serial Number \_\_\_\_\_

Left Rear

Right Rear

Model Number \_\_\_\_\_

\_\_\_\_\_

Serial Number \_\_\_\_\_

\_\_\_\_\_

Machines Possibly Affected:

**SL26/30RT**, 13782 thru 13787, 13792, 13795 thru 13818, 13823, 13830, 13833 thru 13837, 13840,

**XRT**, 3041 thru 3042, 3045 thru 3048, 3050 thru 3051, 3053 thru 3078, 3080 thru 3081, 3083 thru 3089, 3093 thru 3094, 3098 thru 3100,

Please include the following:

Contact Person at Branch/Store \_\_\_\_\_

Branch/Store Phone Number \_\_\_\_\_

Please Fax this completed form to (559) 891-8931

If you have any questions regarding this Service Information Letter, please contact the UpRight Product Support Department by telephone at (800) 926-5438 from within the USA or at (559) 891-5200 outside the USA or by FAX at (559) 891-8931.