

# SERVICE BULLETIN

**Machines/Models:** MX Series  
Work Platforms

**Serial Nos.:** 1028-1037

**SERVICE BULLETIN: 94.5, THE INSTALLATION OF THESE LABELS IS MANDATORY!**

**DATE:** March 21, 1994


**PURPOSE:** Notification of requirement to install labels.

**OPERATION REQUIRED:** Installation of three labels.

**PARTS REQUIRED:** 66555-000, Qty. 1; 62562-001, Qty. 2.

**REIMBURSEMENT:** Three labels are being sent free of charge to the owner of record of each work platform to which this service bulletin is applicable. Installation of the labels will take less than one-quarter hour. UpRight will reimburse the owner of each unit for up to one-quarter hour of installation time at the prevailing shop rate in the owner's shop. UpRight will also reimburse the owner of each unit for reasonable travel time at the rate of USD \$25.00 per hour. Reimbursement will be made upon receipt by UpRight of a properly completed warranty claim.

**PROCEDURE:** Install labels as shown in the following illustration.



If you have any questions regarding this Service Bulletin, please contact the UpRight Product Support Department at (800) 926-5438, in the USA; (209) 896-5150, outside the USA; or by FAX at (209) 896-9244